

Cypres Formed Steel Products, Inc. 784 - TWO EAST 188TH STREET BRONX, N.Y. 10454

John T. Brady & Co., Inc.

June 16, 1972

(Page 2)

COPY

There is no question that negligence existed somewhere between the Dept. of Public Works and John T. Brady & Co., Inc., regarding final inspection, as far as our contract with you. We must hold you responsible, as any objections could have been easily solved and corrected on the ground, and not 3-4 stories in the air.


We do not plan any further expense on our part, as our contract with you does not specifically forbid us the privilege of inscribing our name, as all responsible manufacturers have that right, and do so. Our only regret is that our letters on the Sculpture are too small and not (5") high as claimed by the Dept. of Public Works. We believe it would never be noticed by any of the viewers.

As far as a suggestion of the problem, you can get someone to do the following: Assemble a quantity of the same rust from the surface and mix same with a clear epoxy to be applied just over the area of the letters involved; this will last indefinitely. Do not under any circumstances grind the area, as it would ruin the Sculpture.

We will await your comments.

Yours very truly,

CYPRES FORMED STEEL PRODUCTS, INC.


Paul George
President

P.S. Please advise us who we can hold responsible for storage charges of this Sculpture from the time same was complete until installation time (a period of 2 years).

cc: Dept. of Public Works, Attention: "JPG"
Mr. John Rhoden

pc/km